

EJECTION REPORT

DATE: 5th July 2016

OPERATOR: Brazil

AIRCRAFT TYPE: F-5FM

SEAT TYPE: BR10LF

ALTITUDE: Not known

SPEED: Not known

ATTITUDE: Not known

DETAILS OF INCIDENT

The Brazilian Air Force F-5FM was on a training flight from Santa Cruz Air Base when it experienced a hydraulic emergency which prevented the aircraft landing safely back at the base. The crew directed the aircraft into an uninhabited region and conducted controlled ejections. Both ejections were successful and the crew were picked up straight away.

