

EJECTION REPORT

DATE: 7th January 2018

OPERATOR: Royal Saudi Air Force

AIRCRAFT TYPE: Tornado

SEAT TYPE: SA10A

ALTITUDE: Not known

SPEED: Not known

ATTITUDE: Not known

DETAILS OF INCIDENT

The RSAF Tornado was conducting military operations in Saada province, Yemen when it experienced a technical fault and crashed. Both crew members ejected successfully and were rescued shortly after.

