

## EJECTION REPORT

**DATE:** 13<sup>th</sup> September 2021

**OPERATOR:** Brazil

**AIRCRAFT TYPE:** A-29 (Super Tucano)

**SEAT TYPE:** BR10LCX

**ALTITUDE:** Not known

**SPEED:** Not known

**ATTITUDE:** Not known

### DETAILS OF INCIDENT

The Brazilian Air Force A-29 Super Tucano was conducting a training flight when a suspected engine failure occurred. The pilot directed the aircraft to an open field near Campo Grande airport and ejected. The ejection was successful and the pilot picked up by rescue helicopter and taken to hospital for checks.

